



POWER. PRESENCE.



5 WAYS TO SAVE PIER-SIDE

- 1 Conduct a zone inspection.** Keep doors closed to maintain air conditioning boundaries.
- 2 Turn it off.** Turn off lights and chilled water, and turn off or slow ventilation and exhaust equipment in unmanned spaces.
- 3 Slow fans and pumps.** Doubling the speed requires eight times the power.
- 4 Repair leaks.** Quickly repair leaks and faulty connections. A simple leak can waste up to 30 percent of the compressor's output.
- 5 Train smarter.** Use combat simulators for pier-side training when operationally feasible.

